



Locksmith work on exchangers 290 E 104 AB and 290 E 105 AB. The scope of activities performed included:

- Dismantling and installation of heat exchanger elements and connecting them to the installation of technological pipelines
- Repair work on damaged exchanger parts
- Execution of pressure tests of the jacket and pipe insert of the exchangers, as provided for in the repair technology